

January 29, 1990  
R-6570-JER-2652

Washington State Department of Ecology  
Northwest Regional Office  
4350-150th Avenue Northeast  
Redmond, Washington 98052

**BOEING**

Attention: Pam Elardo  
Water Quality/Chemical Engineer

Subject: Boeing Renton NPDES Permit WA-000299-2  
Spill Report

Reference: Telecon - J. Ramos, Boeing to  
P. Elardo, WDOE  
January 18, 1990, 12:00 pm.


As reported in the referenced telecon, an incident occurred at the Boeing Renton plant on January 9, 1990. Approximately fifty empty paint cans, which originally contained water based latex paint, were left on the pavement from work done in the area. Due to the strong rainstorm occurring at the time, stormwater, slightly discolored by the latex paint, entered Lake Washington from Boeing Renton Outfall 011.

The problem was immediately mitigated by placing the containers in covered, plastic lined tub skids for disposal. An absorbent boom was placed around the nearest catch basin and samples were taken.

An analysis of the stormwater from the affected catch basin and the outfall was performed. The following is a report of the results:

|             | pH  | Cd   | Cr  | Cu   | Pb   | Ni  | Zn  |
|-------------|-----|------|-----|------|------|-----|-----|
| Catch Basin | 7.1 | <.01 | .02 | <.01 | <.01 | .02 | .02 |
| Outfall 011 | 7.2 | .01  | .02 | .01  | .01  | .01 | .02 |

Should you have any questions, please contact Jenette Ramos at 237-9228.



L.M. Babich III  
Manager, Environmental Engineering  
Boeing Renton Division